

# U.S. Department of Homeland Security

# **United States Coast Guard**

# LOCAL NOTICE TO MARINERS WEEKLY EDITION

Week: 21/04 District: 11

> SEND CORRESPONDENCE TO: COMMANDER DISTRICT ELEVEN (OAN) COAST GUARD ISLAND BUILDING 50-3 ALAMEDA, CA 94501-5100

BROADCAST NOTICE TO MARINERS - Information concerning aids to navigation and waterway management promulgated by BNM 0379-04 to BNM 0394-04 has been incorporated in this notice if still significant.

#### **SECTION I - SPECIAL NOTICES**

This section contains information of special concern to the mariner.

#### SUBMITTING INFORMATION FOR PUBLICATION IN THE LOCAL NOTICE TO MARINERS:

A complete set of guidelines with examples and contact information can be found on our website at <a href="http://www.uscg.mil/d11/oan">http://www.uscg.mil/d11/oan</a> or call BM2 Rachel Mentz at (510) 437-2970. LNM 21/04 dated 25 May 2004.

#### dGPS STATUS AS OF 25 May 2004:

For information regarding the dGPS system, or for status updates contact the Petaluma Control Center at (707) 765-7612/ 7613. Proposed off-air dates:

Pigeon Point Primary Date: 1700Z to 1900Z 27 May 2004. Alternate Date: 1700Z to 1900Z 28 May 2004. LNM 21/04 dated 25 May 2004.

LORAN-C STATUS AS OF 25 May 2004: Loran-C stations for 8290 and 9940 Chains are on air. For information regarding the Loran-C System, contact the Coordinator of Chain Operations West Coost at (707) 765-7518. Current Loran-C Status is available 24 hours per days through the Internet at LNM 21/04 dated 25 May 2004.

CHARTS

RNM

T.NM

# SECTION II – DISCREPANCIES

This section lists all reported and corrected discrepancies related to Aids to Navigation in this edition. A discrepancy is a change in the status of an aid to navigation that differs from what is published or charted.

# **DISCREPANCIES**: (bold type and \* denote new information since last LNM)

LLNR	NAME OF AID	STATUS	AFFECTED	REF.	REF.
2255.00	Chula Vista CH LT 21	EXTINGUISHED	18765	0373-04	20-04
3732.00	Ventura Harbor Buoy P	MISSING	18752	0289-04	16-04
<b>DISCREPAN</b> 4050.00 4330.00	CIES CORRECTED: Moss Landing HBR CH Buoy 9 Harding Rock LB HR	WATCHING PROPERLY WATCHING PROPERLY	18686 18649	0379-04 0378-04	20-04

# SECTION III - TEMPORARY CHANGES AND TEMPORARY CHANGES CORRECTED

This section contains temporary changes and corrections to Aids to Navigation for this edition. When charted aids are temporarily relocated for dredging, testing, evaluation, or marking an obstruction, a temporary correction shall be listed in Section IV giving the new position.

TEMPORARY C	HANGES:				
330.00	Pillar PT HBR APP LHB PP	FOG SIGNAL TEMP DISCONTINUED	18680	0071-04	08-04
1595.00	Shelter Island West End LT 2	TRLB	18773	0124-03	04-03
4960.00	San Bruno Shoal CH LT 4	TRLB	18651	1070-03	41-03
6070.00	Petaluma River Entrance CH LT 20	LEANING/TRLB	18654	0362-04	21-04*
6557.00	Suisun Bay CH LT 24A	TRLB	18654	0047-04	03-04
6600.00	New York Slough LT 2	TRLB	18654	1167-03	45-03
6625.00	New York Slough LT 5	TRLB	18654	0839-03	32-03
7945.00	Bodega HBR CH DBN 34	TRUB	18643	0829-03	32-03
TEMPODARY O	HANGES CORRECTED.				
2225.00	HANGES CORRECTED: Chula Vista Channel LT 15	WATCHING PROPERLY	18773	0280-02	14-02

# **SECTION IV - CHART CORRECTIONS**

501	11 <sup>th</sup> ed. 11/01/1997 NAD 83 WEST COAST OF NORTH AMERICA - ME.	Last LNM: 17/04		( CGD11 )	21/04
	Relocate Light FI 10s 148ft 24M Change Light FI 10s 148ft 24M	from 37°10'59.500"N 122°23'42.300"W to FI 10s 148ft 25M	to at	37°10'54.269"N 37°10'54.269"N	122°23'38.199"W 122°23'38.199"W
530	30 <sup>th</sup> ed. 03/23/2002 NAD 83 SAN DIEGO TO ALEUTIAN ISLANDS AND	Last LNM: 17/04		( CGD11 )	21/04
	Relocate Light FI 10s 148ft 24M Change Light FI 10s 148ft 24M	from 37°10'59.500"N 122°23'42.300"W to FI 10s 148ft 25M	to at	37°10'54.269"N 37°10'54.269"N	122°23'38.199"W 122°23'38.199"W
18010	20 <sup>th</sup> ed. 02/01/2001 NAD 83 CA - OR - MONTEREY BAY TO COOS BAY	Last LNM: 20/04		(CGD11)	21/04
	Relocate Light FI 10s 148ft 24M Change Light FI 10s 148ft 24M	from 37°10'59.500"N 122°23'42.300"W to FI 10s 148ft 25M	to at	37°10'54.269"N 37°10'54.269"N	122°23'38.199"W 122°23'38.199"W
18020	36 <sup>th</sup> ed. 01/27/2001 NAD 83 CA - SAN DIEGO TO CAPE MENDOCINO	Last LNM: 20/04		( CGD11 )	21/04
	Relocate Light FI 10s 148ft 24M Change Light FI 10s 148ft 24M Change Light FI 6s 60ft 5M	from 37°10'59.500"N 122°23'42.300"W to FI 10s 148ft 25M to FI 6s 60ft 8M	to at at	37°10'54.269"N 37°10'54.269"N 33°01'25.410"N	122°23'38.199"W 122°23'38.199"W 118°33'49.884"W
18022	34 <sup>th</sup> ed. 11/01/2003 NAD 83	Last LNM: 20/04		( CGD11 )	21/04
	CA - SAN DIEGO TO SAN FRANCISCO BA Change Light FI 6s 60ft 5M	to FI 6s 60ft 8M	at	33°01'25.410"N	118°33'49.884"W
18620	22 <sup>nd</sup> ed. 08/21/1999 NAD 83 CA - POINT ARENA TO TRINIDAD HEAD	Last LNM: 18/04		( CGD11 )	21/04
	Relocate Mooring Buoy	from 40°10'02.682"N 124°03'20.790"W	to	40°00'35.922"N	124°02'59.980"W
18622	53 <sup>rd</sup> ed. 05/01/2004 NAD 83 CA - HUMBOLDT BAY 1 : 25,000 (New edition due to numerous Notice to Mai	NEW EDITION riner changes and various general changes.)		( NOS Silver Spring	g, MD ) 21/04
	This NOAA chart is now available in both the	e Print-on Demand and digital raster formats. e.htm for details. The corresponding traditional pa	per chart v	vill be available in two	to eight weeks.
18649	63 <sup>rd</sup> ed. 09/01/2003 NAD 83 CA - ENTRANCE TO SAN FRANCISCO BA	Last LNM: 20/04		(CGD11)	21/04
	Relocate Lighted Buoy FI G 4s "3" Add Daybeacon "8" Priv	from 37°51'40.737"N 122°27'26.901"W	to at	37°51'40.121"N 37°52'01.000"N	122°27'26.530"W 122°29'23.000"W
18651	41 <sup>st</sup> ed. 02/01/2003 NAD 83 CA - SAN FRANCISCO BAY - SOUTHERN	Last LNM: 12/04		(CGD11)	21/04
	Relocate Light FI R 4s 15ft 4M "8"	from 37°36'16.700"N 122°17'29.000"W	to	37°36'16.622"N	122°17'29.008"W

# **Chart Corrections (Cont)**

18652	32 <sup>nd</sup> ed.	07/01/2003	NAD 83	Last LNM: 20/04		( CGD11)	21/04
	Change Add	ANCISCO BAY Light FI R 2.5s Light FI R 4s 1! Lighted Buoy F Light FI G 4s 2! Light FI R 2.5s Light 25 FI G 4! Daybeacon "36 Daybeacon "8"	20ft 5M "2" 5ft 4M "8" I G 4s "3" Oft 3M "23" 20ft 5M "2" s 15ft 4M "23"	from 38°04'10.700"N 122°14'41.100"W from 37°36'16.700"N 122°17'29.000"W from 37°51'40.737"N 122°27'26.901"W to FI G 4s 20ft 4M "23" to FI R 2.5s 20ft 3M "2"	to to to at at at at at	38°04'10.728"N 37°36'16.622"N 37°51'40.121"N 38°02'36.661"N 38°04'10.728"N 38°16'06.957"N 38°17'11.918"N 37°52'01.000"N	122°14'41.389"W 122°17'29.008"W 122°27'26.530"W 122°10'02.838"W 122°14'41.389"W 122°17'11.960"W 122°17'00.354"W 122°29'23.000"W
18653		09/30/2000	NAD 83	Last LNM: 18/04 ID TO POINT SAN PEDRO		(CGD11)	21/04
	Relocate Add	Light Q W 29ft Daybeacon "8"	3M	from 37°59'52.100"N 121°26'48.700"W	to at	37°59'51.724"N 37°52'01.000"N	121°26'48.974"W 122°29'23.000"W
18654	42 <sup>nd</sup> ed. CA - SAN PA	04/06/2003 BLO BAY	NAD 83	Last LNM: 20/04		(CGD11)	21/04
	Relocate Change Add	Light FI R 2.5s Light FI R 2.5s Light 25 FI G 4: Daybeacon "36	20ft 5M "2" s 15ft 4M "23"	from 38°04'10.700"N 122°14'41.100"W to FI R 2.5s 20ft 3M "2"	to at at at	38°04'10.728"N 38°04'10.728"N 38°16'06.957"N 38°17'11.918"N	122°14'41.389"W 122°14'41.389"W 122°17'11.960"W 122°17'00.354"W
18655	58 <sup>th</sup> ed.	12/22/2001 SLAND STRAIT	NAD 83	Last LNM: 20/04		(CGD11)	21/04
	Relocate Change	Light FI R 2.5s Light FI R 2.5s	20ft 5M "2"	from 38°04'10.700"N 122°14'41.100"W to FI R 2.5s 20ft 3M "2"	to at	38°04'10.728"N 38°04'10.728"N	122°14'41.389"W 122°14'41.389"W
18656	53 <sup>rd</sup> ed. CA - SUISUN	03/01/2003 J BAY	NAD 83	Last LNM: 20/04		(CGD11)	21/04
	Relocate Change	Light FI R 2.5s Light FI G 4s 20 Light FI R 2.5s	Oft 3M "23"	from 38°04'10.700"N 122°14'41.100"W to FI G 4s 20ft 4M "23" to FI R 2.5s 20ft 3M "2"	to at at	38°04'10.728"N 38°02'36.661"N 38°04'10.728"N	122°14'41.389"W 122°10'02.838"W 122°14'41.389"W
18657	18 <sup>th</sup> ed.	03/17/2001 INEZ STRAIT	NAD 83	Last LNM: 14/04		(CGD11)	21/04
	Change	Light FI G 4s 20	Oft 3M "23"	to FI G 4s 20ft 4M "23"	at	38°02'36.661"N	122°10'02.838"W
18660	2 <sup>nd</sup> ed. CA - STOCK Relocate	05/01/2003 TON DEEP WA Light FI R 4s 19		Last LNM: 14/04 - ANTIOCH TO MEDFORD from 38°03'17.400"N 121°31'46.600"W	to	( CGD11 ) 38°03'16.931"N	21/04 121°31'46.218"W
18661	27 <sup>th</sup> ed.	03/01/2003 MENTO AND SA	NAD 83 AN JOAQUIN RI	Last LNM: 16/04		(CGD11)	21/04
	Relocate	Light FI R 4s 19 Light Q W 29ft	9ft 3M "4"	from 38°03'17.400"N 121°31'46.600"W from 37°59'52.100"N 121°26'48.700"W	to to	38°03'16.931"N 37°59'51.724"N	121°31'46.218"W 121°26'48.974"W
18663		01/01/2003	NAD 83	Last LNM: 14/04 EEPWATER CHANNEL-MEDFORD ISLAND T	O STOCKTON	( CGD11 )	21/04
	Relocate	Light Q W 29ft		from 37°59'52.100"N 121°26'48.700"W	to	37°59'51.724"N	121°26'48.974"W
18665	10 <sup>th</sup> ed. CA - NV - LA	06/06/1992 KE TAHOE	NAD 83	Last LNM: 18/04		(CGD11)	21/04
	Relocate	Buoy GC "3"		from 38°57'53.220"N 120°04'55.700"W	to	38°57'50.631"N	120°04'55.093"W
18680	30 <sup>th</sup> ed.	03/03/2001 SUR TO SAN FF	NAD 83	Last LNM: 20/04		(CGD11)	21/04
	Relocate Change	Light FI 10s 14 Light FI 10s 14	8ft 24M	from 37°10'59.500"N 122°23'42.300"W to FI 10s 148ft 25M	to at	37°10'54.269"N 37°10'54.269"N	122°23'38.199"W 122°23'38.199"W
18685	31 <sup>st</sup> ed. CA – MONTE (Inset)	05/16/1998 EREY BAY	NAD 83	Last LNM: 20/04		(CGD11)	21/04
	Delete (Supercedes	Buoy G C "5" P Buoy W Or "E" Buoy W Or "F" LNM 20/04)	Priv		at at at	36°36'32.000"N 36°36'30.000"N 36°36'28.000"N	121°53'34.000"W 121°53'34.000"W 121°53'32.000"W

## **Chart Corrections (Cont)**

18687		11/01/2002	NAD 83	Last LNM: 23/03			(CGD11)	21/04
		RE MEAD Buoy GC "EB-5" Buoy "EB-6"			at	36°18'06 at	.000"N 114°24'4 36°18'10.000"N	4.000"W 114°24'42.000"W
18704	CA - SAN LUI (New edition of This NOAA ch	S OBISPO BAY-POI lue to numerous Not lart is now available	ice to Mari in both the	NEW EDITION  JIS 1: 20,000 ner changes and change in format.) Print-on Demand and digital raster forn .htm for details. The corresponding trace	nats. ditional pap	er chart w	( NOS Silver Sprin	,
18749	38 <sup>th</sup> ed. CA - SAN PEI	12/01/2001	NAD 83	Last LNM: 14/04			(CGD11)	21/04
	Relocate Change Add	Light FI W 4s 30ft 5 Light FI G 2.5s 16ft Light FI 4s 30ft 5M Buoy W Or Priv Buoy W Or Priv Buoy W Or Priv Buoy W Or Priv	:5M "3"	from 33°44'58.500"N 118°11'08.000"V from 33°44'44.000"N 118°06'59.600"V to FI 4s 26ft 7M "J"		to to at at at at at at	33°44'58.782"N 33°44'43.344"N 33°44'58.782"N 33°45'13.920"N 33°45'16.440"N 33°45'18.480"N 33°45'21.480"N	118°11'07.662"W 118°06'59.904"W 118°11'07.662"W 118°11'12.000"W 118°11'08.700"W 118°11'05.700"W 118°11'05.500"W
18751	42 <sup>nd</sup> ed.	12/01/2001		Last LNM: 17/04			(CGD11)	21/04
	CA - LOS AND Relocate Change Add	GELES AND LONG I Light FI W 4s 30ft 5 Pier J Light J Buoy W Or Priv Buoy W Or Priv Buoy W Or Priv Buoy W Or Priv		ARBORS from 33°44'58.500"N 118°11'08.000"V from Fl 4s 30ft 5M "J" to Fl 4s 26ft 7M		to at at at at at	33°44'58.782"N 33°44'58.782"N 33°45'13.920"N 33°45'16.440"N 33°45'18.480"N 33°45'21.480"N	118°11'07.662"W 118°11'07.662"W 118°11'12.000"W 118°11'18.700"W 118°11'05.700"W 118°11'05.500"W
18754	17 <sup>th</sup> ed. CA - NEWPOI	07/01/2003	NAD 83	Last LNM: 18/04			(CGD11)	21/04
	Change	Light FI G 4s 15ft 5 Light FI R 4s 19ft 5	M "11" M "8"	to FI G 4s 15ft 4M "11" to FI R 4s 19ft 3M "8"		at at	33°36'28.746"N 33°36'05.034"N	117°54'15.276"W 117°53'14.610"W
18762	15 <sup>th</sup> ed.	06/06/1998 EMENTE ISLAND	NAD 83	Last LNM: 09/04			(CGD11)	21/04
	Change Change	Light FI 6s 60ft 5M		to FI 6s 60ft 8M		at	33°01'25.410"N	118°33'49.884"W
18763	10 <sup>th</sup> ed. CA - SAN CLE	02/01/2004 EMENTE ISLAND - N		Last LNM: 18/04 N PART			(CGD11)	21/04
	Change	Light FI 6s 60ft 5M		to FI 6s 60ft 8M		at	33°01'25.410"N	118°33'49.884"W

# **SECTION V - ADVANCE NOTICES**

This section contains advance notice of approved projects, changes to aids to navigation, or upcoming temporary changes such as dredging, etc.

Mariners are advised to use caution when transiting these areas.

#### None.

## **SECTION VI - PROPOSED CHANGES**

Periodically, the Coast Guard evaluates its system of aids to navigation to determine whether the conditions for which the aids to navigation were established have changed. When changes occur, the feasibility of improving, relocating, replacing, or discontinuing aids are considered. This section contains notice(s) of non-approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond to the District Office unless otherwise noted.

None.

#### **SECTION VII – GENERAL**

This section contains information of general concern to the Mariners. Mariners are advised to use caution while transiting these areas.

All times are given in local time, represented by the time followed by (T).

**GENERAL INFORMATION – SAN DIEGO BAY –** NAVIGATION INFORMATION - The San Diego Entrance Range aligns at a bearing of 353.5° True, compared to the channel alignment of 353.0° True. When the range aligns, the inbound mariner will be on the port hand side of the channel. Chart: 18772 LNM 21/04 dated 25 May 2004.

**SOUTHERN CALIFORNIA – SAN DIEGO BAY –** DIVING OPERATIONS – The Naval Pubic Works divers will be conducting diving operations **from 0600T to1800T through 27 May 2004** in Marina Del Rey Harbor. SCUBA divers will be conducting operations from a 27' Boston Whaler. Diving will be taking place between the breakwater and North and South Jetty lights at harbor entrance. Operations will also be conducted approximately 3500 feet inside harbor entrance. Divers will be monitoring VHF-FM Ch. 16 and 14 and will have cell phone 619-571-4156.Mariners are advised to use caution when transiting the area. For further comments or details, contact John Holtermann at (619) 556-8623. Chart: 18772 LNM 21/04 dated 25 May 2004.

NORTHERN CALIFORNIA – SAN FRANCISCO BAY – MARINE EVENTS – Please refer to the Yacht Race Association website: <a href="https://www.YRA.org">www.YRA.org</a> for yacht race schedules in the SF Bay. For further comments or details, contact MST1 Brian Clark at (415) 399-3440. Chart: None LNM 21/04 dated 25 May 2004.

**NORTHERN CALIFORNIA – OAKLAND INNER HARBOR –** ABANDONED TUG – An abandoned tug is located on the Alameda side of the Park Street Bridge Reach Section of the Oakland Inner Harbor approximately 200 yards west of the bridge. The tug protrudes into the channel and all mariners are advised to use caution when transiting the area. The tug will be removed **by 15 July 2004**. For further comments or details, contact Lieutenant Doug Ebbers at (510) 437-2770.

Chart: 18650 LNM 21/04 dated 25 May 2004.

ARIZONA - COLORADO RIVER - MARINE EVENT – The AVI Resort And Casino Memorial Day fireworks will take place from 2015T to 2115T on 30 May 2004 and will consist of a 25 min firework display in the area of the AVI Resort and Casino. The established Safety Zone will restrict all vessel traffic (commercial and recreational) 15 minutes prior to firing time until completion of the display. During the event, PATCOM may be reached via VHF-FM Ch. 16. For further comments or details, contact Rob Wilson at (702) 299-5156 or OSC Doug Samp, Coast Guard San Diego Marine Events Coordinator, at (619) 683-6309.

Chart: None LNM 21/04 dated 25 May 2004.

**BRIDGE INFORMATION - DISCREPANCIES AND CORRECTIONS -** Questions regarding bridge operations, discrepancies, regulations or permit applications, please contact: Eleventh Coast Guard District Bridge Section, Coast Guard Island, Building 50-3, Alameda, CA 94501-5100 Phone: (510) 437-3514 or the Coast Guard Command Center at (510) 437-3701. Flotsam and drift may have accumulated on and near bridge piers and abutments and mariners should approach all bridges with caution.

NORTHERN CALIFORNIA - CARQUINEZ STRAIT — NEW I-680 HIGHWAY BRIDGE CONSTRUCTION — Barge anchor wires extend parallel to the main navigation channel as much as 900 ft upstream and downstream from barges at the main navigation opening of the bridge. Anchors upstream of the construction site will be approx 50 ft outside the north and south margins of the Federal channel from 07 Jun through 15 Jul 2004. Anchor wires can be moved upon 3 hours advance notice when a tug is present and 6 hours when a tug is not present. Mariners should contact the Westar Mariner Tug at Benicia Bridge via VHF-FM Ch. 13 to make passing arrangements. Bridge pier construction is in progress along the entire length of the bridge, with anchor lines extending 800 ft upstream and downstream from the bridge. Anchor wires may be difficult to see and mariners are advised, for their own safety, to avoid passing through the construction area by going around the construction and using the main navigational channel. For work away from the main channel span, mariners should contact the D/B PACIFIC, the D/B HAAKEN, or the D/B LA via VHF-FM Ch. 13, 14, and 67 to discuss wake issues and passing arrangements.

Chart: 18657 LNM 21/04 dated 25 May 2004.

## **SECTION VIII - LIGHT LIST CORRECTIONS**

An asterisk \*, indicates the column in which a correction has been made to new information. Corrections in this section are intended for Light List Volume VI, which can be found at <a href="http://www.navcen.uscg.gov/pubs/LightLists/V6COMPLETE.PDF">http://www.navcen.uscg.gov/pubs/LightLists/V6COMPLETE.PDF</a> and is corrected online through LNM 05/04.

(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	
No.	Name and location	Position	Characteristic	Height	Range	Structure	Remarks	
6214	- Buoy BP	38 03 40 N 122 13 39 W				Red and green. bands.		20/04

#### **SECTION IX - PUBLICATION CORRECTIONS**

This section contains changes to the Coast Pilot Volume 7.

The Coast Pilot can be found online at <a href="http://nauticalcharts.noaa.gov/nsd/cpdownload.htm">http://nauticalcharts.noaa.gov/nsd/cpdownload.htm</a>.

None.

# **SECTION X - ENCLOSURES**

None.

A. J. Shaw Commander, U.S. Coast Guard Chief, Aids to Navigation and Waterways Management Branch